









AS-13-WB
LN-13-LV
LN-23-LV
RA-13-LV
RA-23-LV


MIROMARK
ФАБРИКА МЕБЛІВ








A1 - 2104 x 530 x 16 - x 1
A2 - 2104 x 530 x 16 - x 1
B - 2104 x 516 x 16 - x 1
C1 - 872 x 516 x 16 - x 1
C2 - 872 x 516 x 16 - x 1
C3 - 872 x 516 x 16 - x 1
D1 - 424 x 516 x 16 - x 1
D2 - 424 x 516 x 16 - x 1
D3 - 424 x 516 x 16 - x 1
F1 - 872 x 50 x 16 - x 2
F2 - 424 x 50 x 16 - x 2


G1 - 2054 x 442 x 3 - x 2
G2 - 2054 x 437 x 3 - x 1
H - 2050 x 444 x 16 - x 1
I - 2050 x 444 x 16 - x 1
J - 2050 x 444 x 16 - x 1
K - 2132 x 110 x 28 - x 1
L - 2132 x 110 x 28 - x 1
M - 1345 x 110 x 28 - x 1
R1 - 865 - x 1
R2 - 417 - x 1
Z - 2000MM x 1

1 $\varnothing 8 \times 50$ x8

21850

2 $\varnothing 8 \times 30$ x18

21008

3 x6

14010

4 $\varnothing 4 \times 16$ x34

10416

5 x10

08003

6 35mm x2
(H)

03357

7 35mm x2
(G)


03362


8 35mm x4
(B)


03360


9 35mm x4
(A)


03359


10 x12

11002


11 x4

11062

12 x20

11016

13 x8

10010


14 $\varnothing 4.2 \times 19$ x65

10419


15 $\varnothing 4.2 \times 13$ x4

10413


16 x4

80333

17 $\varnothing 4.2 \times 32$ x6

10432


18 $\varnothing 6.3 \times 13$ x24

10613


19 x2

19057

20 $\varnothing 8 \times 50$ x2

10016

21 $\varnothing 5 \times 60$ x2


10443


22 x2

08011

23 x1

19067


24 $\varnothing 3.5 \times 15$ x10




10315



25 x16

00212


26 $\varnothing 3 \times 16$ x4

10316















Z 1 = 249
Z 2 = 313
Z 3 = 377





a=b

