










FM-13-WB

**MIROMARK**  
ФАБРИКА МЕБЛІВ




11-IZ-290  
(H)







**A1**-2104x 530 x 16 - x 1  
**A2**-2104x 530 x 16 - x 1  
**B** -2104x 516 x 16 - x 1  
**C1**- 872 x 516 x 16 - x 1  
**C2**- 872 x 516 x 16 - x 1  
**C3**- 872 x 516 x 16 - x 1  
**D1**- 424 x 516 x 16 - x 1  
**D2**- 424 x 516 x 16 - x 1  
**D3**- 424 x 516 x 16 - x 1

**F1** - 872 x 50 x 16 - x 2  
**F2** - 424 x 50 x 16 - x 2  
**G1**-2054x 442 x 3 - x 2  
**G2**-2054x 438 x 3 - x 1  
**H** -2050x 444 x 16 - x 2  
**I** -2050x 444 x 16 - x 1  
**R1**- 865 - x 1  
**R2**- 417 - x 1  
**Z** -2000MM x 1


①  $\varnothing 8 \times 50$  x8  
  
**21850**


②  $\varnothing 8 \times 30$  x16  
  
**21008**


③ x6  
  
**14010**


④  $\varnothing 4 \times 16$  x35  
  
**10416**


⑤ 35mm x4  
  
**60605**


⑥ 35mm x8  
  
**57602**


⑦ x16  
  
**00212**


⑧  $\varnothing 6.3 \times 13$  x24  
  
**10613**


⑨ x10  
  
**08003**

⑩ x8  
  
**11002**


⑪ x4  
  
**11062**

⑫ x16  
  
**11016**


⑬ x8  
  
**10010**

⑭  $\varnothing 4.2 \times 19$  x65  
  
**10419**


⑮ x3  
  
 $\varnothing 4 \times 22$  \* x2  
**19081**


⑯ x4  
  
**80333**

⑰  $\varnothing 3.5 \times 15$  x8  
  
**10315**


⑱  $\varnothing 8 \times 50$  x2  
  
**10016**




⑲  $\varnothing 5 \times 60$  x2  
  
**10443**



⑳ x2  
  
**08011**



㉑  $\varnothing 4.2 \times 13$  x4  
  
**10413**
















$a=b$

