











LZ-14-WB
LZ-24-WB


MIROMARK
ФАБРИКА МЕБЛІВ








A1 - 2104 x 530 x 16 - x 1
A2 - 2104 x 530 x 16 - x 1
B - 2104 x 516 x 16 - x 1
C1 - 872 x 516 x 16 - x 2
C2 - 872 x 516 x 16 - x 2
C3 - 872 x 516 x 16 - x 2
D - 872 x 50 x 16 - x 4
E - 2054 x 442 x 3 - x 4


F - 2050 x 444 x 16 - x 2
H - 2050 x 444 x 16 - x 2
J - 596 x 97 x 25 - x 1
K - 596 x 97 x 25 - x 1
L - 1924 x 97 x 25 - x 1
R - 865MM - x 2
Z - 2000MM x 2


① $\varnothing 8 \times 50$ x8

21850


② $\varnothing 8 \times 30$ x16

21008

③ x6

14010

④ $\varnothing 4 \times 16$ x43

10416

⑤ x10

08003

⑥ 35mm x4
D

03357


⑦ 35mm x4
C

03362

⑧ 35mm x4
B

03360


⑨ 35mm x4
A


03359


⑩ x8

11002


⑪ x4

11062

⑫ x16

11016

⑬ x8

10010

⑭ $\varnothing 4.2 \times 19$ x65

10419


⑮ x4

80333

⑯ $\varnothing 3.5 \times 15$ x8

10315


⑰ x4
 $\varnothing 4 \times 22$


19016


⑱ $\varnothing 8 \times 50$ x2

10016

⑲ $\varnothing 5 \times 60$ x2

10443


⑳ x2

08011


㉑ $\varnothing 4.2 \times 13$ x4

10413


㉒ $\varnothing 6.3 \times 13$ x16

10613


㉓ x8

26700






㉔ $\varnothing 4 \times 10$ x16

10410




㉕ x16

00212



㉖ x2

08010


㉗ x4
 $\varnothing 4.2 \times 19$

10419











Z 1 = 249
Z 2 = 313
Z 3 = 377

