








FM-26-WB
*FM-16-WB


MIROMARK
ФАБРИКА МЕБЛІВ








A1-2104x 530 x 16 - x 1
A2-2104x 530 x 16 - x 1
B -2104x 516 x 16 - x 2
C1- 872 x 516 x 16 - x 2
C2- 872 x 516 x 16 - x 2
C3- 872 x 516 x 16 - x 2
D1- 880 x 516 x 16 - x 1
D2- 880 x 516 x 16 - x 1
D3- 880 x 516 x 16 - x 1


F1- 872 x 50 x 16 - x 4
F2- 880 x 50 x 16 - x 2
G1-2054x 442 x 3 - x 4
G2- 2054x 446 x 3 - x 2
H -2050x 444 x 16 - x 2
I -2050x 444 x 16 - x 4
R1- 865 x 2
R2- 873 x 1
Z -2000MM x 3


① $\varnothing 8 \times 50$ x16

21850


② $\varnothing 8 \times 30$ x16

21008

③ x8

14010

④ $\varnothing 4 \times 16$ x59

10416


⑤ x10

08003


⑥ 35mm x8
D

03357

⑦ 35mm x8
C

03362

⑧ 35mm x4
B


03360


⑨ 35mm x4
A

03359


⑩ x8

11002


⑪ x8


11062


⑫ x24

11016

⑬ x12

10010

⑭ $\varnothing 4.2 \times 19$ x90

10419


⑮ x6
 * x4
 $\varnothing 4 \times 22$

19081


⑯ * x1

19057

⑰ x6

80333

⑱ $\varnothing 3.5 \times 15$ x12


10315


⑲ $\varnothing 4.2 \times 13$ x4

10413

⑳ $\varnothing 8 \times 50$ x2

10016

㉑ $\varnothing 5 \times 60$ x2


10443


㉒ x2

08011


㉓ $\varnothing 6.3 \times 13$ x16

10613

㉔ x16






26700


㉕ $\varnothing 4 \times 10$ x32

10410



㉖ x24

00212





㉗ * x2
 $\varnothing 3 \times 16$

10316

















$a=b$

